



*Cofe*

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE PATENT APPLICATION OF:

Our File: 29-34 US

Serial No: 10/715,165

Group: 2811

Patent No: 6,906,353

Issued: June 14, 2005

Title: HIGH SPEED IMPLANTED VCSEL

April 26, 2006

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**Certificate**  
**MAY 04 2006**  
**of Correction**

Dear Sir:

We respectfully request the correction of errors as set out in the attached Certificate of Correction. It is our understanding that, since these errors occurred in the United States Patent and Trademark Office, no fee is required.

The Commissioner is hereby authorized to charge any fees which may be required, or credit any overpayment, to Deposit Account 50-1465.

Respectfully,

Neil Teitelbaum  
Regn No: 38,793

Customer No: 24949

Teitelbaum & MacLean  
Registered Patent Agents Limited  
1187 Bank Street, Ste 201  
Ottawa, Ontario, K1S 3X7  
Canada

Tel: (613) 523 3784  
Fax: (613) 523 6799  
Email: [nt@patents.org](mailto:nt@patents.org)  
[www.patents.org](http://www.patents.org)

/ewg

**MAY 04 2006**

**UNITED STATES PATENT AND TRADEMARK OFFICE**

**CERTIFICATE OF CORRECTION**

**PATENT NO:** 6,906,353

**DATED:** June 14, 2005

**INVENTOR(S):** Shieh et al

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Col. 9, line 12, "produce" should read – provide --

In Col. 10, line 29, "retraction" should read – refraction --

**MAILING ADDRESS OF SENDER:**

**PATENT NO. 6,906,353**

Teitelbaum & MacLean  
Registered Patent Agents Limited  
1187 Bank Street, Ste 201  
Ottawa, Ontario  
Canada  
K1S 3X7

Tel: (613) 523 3784  
Fax: (613) 523 6799  
Email: nt@patents.org  
www.patents.org

Form PTO 1050

**MAY 04 2006**